



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 21-03-05591

Client: Stohl Environmental
 3860 California Road
 Orchard Park, NY 14127

Received Date: 03/25/2021
Reported Date: 04/22/2021
Sampled By: Paul Nichols
Tech Certification #:

Project/Test Address: 2020L-149.13; Admin Building; 630 66th St; Niagara Falls, NY

Client Number:
 33-5980

Laboratory Results

Fax Number:
 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-05591-001	149.13-3	03/18/2021	ROOM 210	2.66	04/21/2021	
21-03-05591-002	149.13-4	03/18/2021	ROOM 210 BATHROOM	5.85	04/21/2021	
21-03-05591-003	149.13-5	03/18/2021	ROOM 223 BATHROOM	1.94	04/21/2021	
21-03-05591-004	149.13-6	03/18/2021	ROOM 211 BATHROOM	9.05	04/21/2021	
21-03-05591-005	149.13-7	03/18/2021	ROOM 222 BATHROOM	6.03	04/21/2021	
21-03-05591-006	149.13-8	03/18/2021	ROOM 222 BATHROOM	18.2	04/21/2021	
21-03-05591-007	149.13-9	03/18/2021	ROOM 212 BATHROOM	5.92	04/21/2021	
21-03-05591-008	149.13-10	03/18/2021	ROOM 212	10.6	04/21/2021	
21-03-05591-009	149.13-11	03/18/2021	ROOM 212 BATHROOM	2.94	04/21/2021	
21-03-05591-010	149.13-12	03/18/2021	ROOM 221	18.0	04/21/2021	
21-03-05591-011	149.13-14	03/18/2021	ROOM 221 BATHROOM	2.85	04/21/2021	
21-03-05591-012	149.13-17	03/18/2021	ROOM 214 BATHROOM	9.79	04/21/2021	
21-03-05591-013	149.13-18	03/18/2021	ROOM 219A	2.03	04/21/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-03-05591

Project/Test Address: 2020L-149.13; Admin Building; 630 66th St; Niagara Falls, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-05591-014	149.13-19	03/18/2021	ROOM 219B BATHROOM	4.41	04/21/2021	
21-03-05591-015	149.13-20	03/18/2021	ROOM 218B BATHROOM	5.15	04/21/2021	
21-03-05591-016	149.13-21	03/18/2021	ROOM 215 BATHROOM	8.79	04/21/2021	
21-03-05591-017	149.13-22	03/18/2021	HALLWAY NEAR ROOM 216 A BATHROOM	<1.00	04/21/2021	
21-03-05591-018	149.13-23	03/18/2021	ROOM 216 BATHROOM	3.85	04/21/2021	
21-03-05591-019	149.13-24	03/18/2021	HALLWAY NEAR ROOM 217 BATHROOM	9.28	04/21/2021	
21-03-05591-020	149.13-25	03/18/2021	ROOM 106 BATHROOM	26.8	04/21/2021	
21-03-05591-021	149.13-26	03/18/2021	ROOM 105 BATHROOM	12.4	04/21/2021	
21-03-05591-022	149.13-27	03/18/2021	ROOM 107 BATHROOM	11.2	04/21/2021	
21-03-05591-023	149.13-28	03/18/2021	ROOM 104 BATHROOM	3.82	04/21/2021	
21-03-05591-024	149.13-29	03/18/2021	ROOM 103A BATHROOM	8.06	04/21/2021	
21-03-05591-025	149.13-30	03/18/2021	ROOM 102A BATHROOM	2.81	04/22/2021	
21-03-05591-026	149.13-31	03/18/2021	ROOM 109	357	04/21/2021	
21-03-05591-027	149.13-33	03/18/2021	ROOM 109 BATHROOM	32.5	04/21/2021	
21-03-05591-028	149.13-34	03/18/2021	ROOM 109 BATHROOM	25.7	04/21/2021	
21-03-05591-029	149.13-35	03/18/2021	ROOM 101	12.8	04/21/2021	
21-03-05591-030	149.13-36	03/18/2021	ROOM 110A BATHROOM	2.58	04/21/2021	
21-03-05591-031	149.13-37	03/18/2021	ROOM 110A BATHROOM	5.26	04/21/2021	
21-03-05591-032	149.13-38	03/18/2021	ROOM 110A	4.43	04/21/2021	
21-03-05591-033	149.13-39	03/18/2021	HALLWAY NEAR SIGN SHOP	<1.00	04/21/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980
Project/Test Address: 2020L-149.13; Admin Building; 630 66th St; Niagara Falls, NY

Report Number: 21-03-05591

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-05591-034	149.13-40	03/18/2021	SIGN SHOP	23.1	04/21/2021	
21-03-05591-035	149.13-43	03/18/2021	WOMENS LAV NEAR CLERKS OFFICE	6.95	04/21/2021	
21-03-05591-036	149.13-44	03/18/2021	MENS LAV NEAR CLERKS OFFICE	<1.00	04/21/2021	
21-03-05591-037	149.13-45	03/18/2021	EXECUTIVE BOARD ROOM	<1.00	04/21/2021	
21-03-05591-038	149.13-46	03/18/2021	EXECUTIVE BOARD ROOM LAV	3.31	04/21/2021	
21-03-05591-039	149.13-48	03/18/2021	ELECTRICAL STORE ROOM LAV	3.20	04/21/2021	
21-03-05591-040	149.13-51	03/18/2021	ELECTRICAL ROOM DF	7.46	04/21/2021	
21-03-05591-041	149.13-52	03/18/2021	EXECUTIVE BOARD ROOM ICE MACHINE	17.2	04/21/2021	

Method: EPA 200.8
Analyst: Anthony Dee
Accreditation #: NY 11714

Reviewed By Authorized Signatory: *Melissa Kanode*

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.13

Client: Niagara Falls CSD

Contact: Earl Smeal

Building: Admin Building

Location: 630 66th St, Niagara Falls, NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
149.13-3	Room 210	S	2:30
149.13-4	room 210 - bathroom	S	2:31
149.13-5	room 223 - bathroom	S	2:32
149.13-6	room 211 - bathroom	S	2:33
149.13-7	Room 222 - bathroom	S	2:34
149.13-8	room 222 - bathroom	S	2:35
149.13-9	Room 212 - bathroom	S	2:36
149.13-10	room 212	S	2:37
149.13-11	room 212 - bathroom	S	2:38
149.13-12	room 221	S	2:39
149.13-14	room 221 - bathroom	S	2:40
149.13-17	room 214 - bathroom	S	2:41
149.13-18	room 219A	S	2:42
149.13-19	room 219B - bathroom	S	2:43
149.13-20	room 218b - bathroom	S	2:44
149.13-21	room 215 - bathroom	S	2:45
149.13-22	hallway near room 216a - bathroom	S	2:46
149.13-23	room 216 - bathroom	S	2:47

21-03-05591



Due Date:
 04/22/2021
 (Thursday)
 AE

KH

Notes:

Please e-mail lab results to labs@stohlenv.com If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 3/18/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 3/22/2021

Received (Name / Lab): T. Henderson Date: 3/25/21 Time: 3:16

Sample Login (Name / Lab): M. Smeal Date: 4/22/21 Time: P. Henderson

Analysis (Name / Lab): Earl Smeal Date: 4/22/21 Time: 3:16pm

QA/QC Review (Name / Lab): M. Smeal Date: 4/22/21 Time: P. Henderson

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.13

Client: Niagara Falls CSD

Contact: Earl Smeal

Building: Admin Building

Location: 630 66th St, Niagara Falls, NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
149.13-24	hallway near room 217 - bathroom	S	2:48
149.13-25	room 106 - bathroom	S	2:49
149.13-26	room 105 - bathroom	S	2:50
149.13-27	room 107 - bathroom	S	2:51
149.13-28	room 104 - bathroom	S	2:52
149.13-29	room 103a - bathroom	S	2:53
149.13-30	room 102a - bathroom	S	2:54
149.13-31	room 109	S	2:55
149.13-33	room 109 - bathroom	S	2:56
149.13-34	room 109 - bathroom	S	2:57
149.13-35	room 101	S	2:57
149.13-36	room 110a - bathroom	S	2:58
149.13-37	room 110a - bathroom	S	2:59
149.13-38	room 110a	S	3:00
149.13-39	hallway near sign shop	DF	3:01
149.13-40	sign shop	S	3:02
149.13-43	women's lav near clerks office	S	3:03
149.13-44	men's lav near clerks office	S	3:04

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 3/18/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 3/22/2021

Received (Name / Lab): T. Johnson Date: 3/25/21 Time: 3:15

Sample Login (Name / Lab): M. Miller Date: 4/1/21 Time: 4:00pm

Analysis (Name / Lab): Mary O'Connell Date: 4/1/21 Time: 3:15pm

QA/QC Review (Name / Lab): M. Miller Date: 4/1/21 Time: 4:00pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.13

Client: Niagara Falls CSD Contact: Earl Smeal

Building: Admin Building Location: 630 66th St, Niagara Falls, NY

LEAD	Turnaround
Water by SM 19, 21 - 23 3113B (-04, -10) <u>X</u>	<u>20 Days</u>

Sample #	Location	Outlet Type	Time
149.13-45	executive board room	S	3:05
149.13-46	executive board room lav	S	3:06
149.13-48	electrical store room lav	S	3:08
149.13-51	Electrical Room DF	DF	3:09
149.13-52	Executive Board Room Ice Machine	IM	3:10

Notes:
 Please e-mail lab results to labs@stohlenv.com Ehenderson@StohlEnv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 3/18/2021

Relinquished By: *Eric Henderson Jr.* Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 3/22/2021

Received (Name / Lab): *T. H. Henderson* Date: *3/25/21* Time: *3:15*

Sample Login (Name / Lab): *Meluh* Date: *4/1/21* Time: *4:00*

Analysis (Name / Lab): *Gary Duce* Date: *4/1/21* Time: *3:15*

QA/QC Review (Name / Lab): *Meluh* Date: *4/1/21* Time: *4:00*

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____