

Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237 Telephone: 800.347.4010 Lead in Drinking Water Analysis Report

Report Number: 21-04-04642

Stohl Environmental

3860 California Road Orchard Park, NY 14127 Received Date: 04/27/2021
Reported Date: 06/01/2021
Sampled By: Paul Nichols

Tech Certification #:

Project/Test Address: 2020L-149.7; Maple Ave Elementary School; 952 Maple Ave; Niagara Falls,

NY

Client Number:

33-5980

Client:

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-04642-001	149.7-1	03/19/2021	LEFT BATHROOM NEAR PRINCIPLES OFFICE	1.11	05/26/2021	
21-04-04642-002	149.7-2	03/19/2021	LOUNGE NEAR PRINCIPLES OFFICE	<1.00	05/26/2021	
21-04-04642-003	149.7-3	03/19/2021	RIGHT BATHROOM NEAR PRINCIPLES OFFICE	<1.00	05/26/2021	
21-04-04642-004	149.7-4	03/19/2021	GIRLS BATHROOM NEAR CAFE	<1.00	05/26/2021	
21-04-04642-005	149.7-5	03/19/2021	BOYS BATHROOM NEAR CAFE LEFT	<1.00	05/26/2021	
21-04-04642-006	149.7-6	03/19/2021	LEFT TRIPLE SINK	<1.00	05/26/2021	
21-04-04642-007	149.7-7	03/19/2021	RIGHT TRIPLE SINK	<1.00	05/26/2021	
21-04-04642-008	149.7-8	03/19/2021	ISLAND SINK	<1.00	05/26/2021	
21-04-04642-009	149.7-9	03/19/2021	HAND WASH SINK	1.07	05/26/2021	
21-04-04642-010	149.7-10	03/19/2021	RM 6	<1.00	05/26/2021	
21-04-04642-011	149.7-12	03/19/2021	RM 5	<1.00	05/26/2021	
21-04-04642-012	149.7-13	03/19/2021	CLINIC BATHROOM	<1.00	05/26/2021	

Environmental Hazards Services, L.L.C

Report Number:

21-04-04642

Client Number:

33-5980

Project/Test Address: 2020L-149.7; Maple Ave Elementary School; 952 Maple Ave; Niagara Falls, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-04642-013	149.7-14	03/19/2021	CLINIC	<1.00	05/26/2021	
21-04-04642-014	149.7-16	03/19/2021	RM 4	<1.00	05/26/2021	
21-04-04642-015	149.7-17	03/19/2021	RM 4	1.10	05/26/2021	
21-04-04642-016	149.7-19	03/19/2021	RM 3	<1.00	05/26/2021	
21-04-04642-017	149.7-20	03/19/2021	RM 3	<1.00	05/26/2021	
21-04-04642-018	149.7-21	03/19/2021	RM 2	9.29	05/26/2021	
21-04-04642-019	149.7-22	03/19/2021	RM 2	17.6	05/26/2021	
21-04-04642-020	149.7-23	03/19/2021	RM 1	31.4	05/26/2021	
21-04-04642-021	149.7-24	03/19/2021	RM 1	19.8	06/01/2021	
21-04-04642-022	149.7-25	03/19/2021	BOYS BATHROOM LEFT	1.08	05/26/2021	
21-04-04642-023	149.7-26	03/19/2021	GIRLS BATHROOM LEFT	5.18	05/26/2021	
21-04-04642-024	149.7-27	03/19/2021	RM 22	<1.00	05/26/2021	
21-04-04642-025	149.7-29	03/19/2021	RM 21	<1.00	05/26/2021	
21-04-04642-026	149.7-30	03/19/2021	RM 21	<1.00	05/26/2021	
21-04-04642-027	149.7-31	03/19/2021	RM 20	<1.00	05/26/2021	
21-04-04642-028	149.7-32	03/19/2021	RM 20	1.36	05/26/2021	
21-04-04642-029	149.7-33	03/19/2021	GIRLS BATHROOM LEFT	<1.00	05/26/2021	
21-04-04642-030	149.7-38	03/19/2021	BOYS BATHROOM LEFT	2.53	05/26/2021	
21-04-04642-031	149.7-39	03/19/2021	RM 9	<1.00	05/26/2021	
21-04-04642-032	149.7-42	03/19/2021	CUSTODIANS OFFICE	<1.00	05/26/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-04-04642

Project/Test Address: 2020L-149.7; Maple Ave Elementary School; 952 Maple Ave; Niagara Falls, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-04-04642-033	149.7-44	03/19/2021	KITCHEN IM	<1.00	05/26/2021	
21-04-04642-034	149.7-45	03/19/2021	KITCHEN SPRAYER	<1.00	05/26/2021	
21-04-04642-035	149.7-46	03/19/2021	BOYS BATHROOM NEAR CAFE MIDDLE	<1.00	05/26/2021	
21-04-04642-036	149.7-47	03/19/2021	BOYS BATHROOM NEAR CAFE RIGHT	<1.00	05/26/2021	
21-04-04642-037	149.7-48	03/19/2021	RM 6 BUBBLE	2.48	05/26/2021	
21-04-04642-038	149.7-49	03/19/2021	RM 5 BUBBLE	<1.00	05/26/2021	
21-04-04642-039	149.7-50	03/19/2021	ADMIN ROOM BR	4.32	05/26/2021	
21-04-04642-040	149.7-51	03/19/2021	BOYS LOCKER ROOM	<1.00	05/26/2021	
21-04-04642-041	149.7-52	03/19/2021	GIRLS LOCKER ROOM	5.14	05/26/2021	
21-04-04642-042	149.7-53	03/19/2021	1ST FLOOR GIRLS BR NEAR STAIRS MIDDLE	<1.00	05/26/2021	
21-04-04642-043	149.7-54	03/19/2021	1ST FLOOR GIRLS BR NEAR STAIRS RIGHT	<1.00	05/26/2021	
21-04-04642-044	149.7-55	03/19/2021	1ST FLOOR BOYS BR NEAR STAIRS MIDDLE	1.57	05/26/2021	
21-04-04642-045	149.7-56	03/19/2021	1ST FLOOR BOYS BR NEAR STAIRS RIGHT	1.82	05/26/2021	
21-04-04642-046	149.7-57	03/19/2021	2ND FLOOR GIRLS BR MIDDLE	<1.00	05/26/2021	
21-04-04642-047	149.7-58	03/19/2021	2ND FLOOR GIRLS BR RIGHT	<1.00	05/26/2021	
21-04-04642-048	149.7-59	03/19/2021	2ND FLOOR BOYS BR MIDDLE	1.48	05/26/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-04-04642

Project/Test Address: 2020L-149.7; Maple Ave Elementary School; 952 Maple

Ave; Niagara Falls, NY

Lab Sample Client Collection Collection Location Concentration Analysis Narrative
Number Sample ID Date ID

Method: EPA 200.8
Analyst: Anthony Dee
Accreditation #: NY 11714

Reviewed By Authorized Signatory:

_____ Missy Kanode

Milisoa Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND

ug/L= micrograms per liter

ppb = parts per billion



Chain of Custody Document

Submitted to: (Lab Name)

STOHL Job#

EHS

2020L-149.7

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM

Notes:

	 	 	_	 	_

				Market and the second s	
Client:	Niagara Falls CSD	Conta	ct: Earl Smeal		
Building:	Maple Ave Elementary School	Location: 952 Maple Ave. Niagara Falls, NY			
LEAD			Turnaround		
Water by	SM 19, 21 - 23 3113B (-04, -10)	Χ	20 Days		

Sample #	Lo	cation	Outlet Type	Time
149.7-1	Left Bathroom Near Principles Office		S	22:30
149.7-2	Lounge Near Principles Office		S	22:31
149.7-3	Right Bathroom Near Principles Office		S	22:32
149.7-4	Girls Bathroom Near Cafe		S	22:33
149.7-5	Boys Bathroom Near Cafe left		S	22:34
149.7-6	Left Triple sink		S	22:35
149.7-7	Right Triple sink		S	22:36
149.7-8	Island Sink		S	22:3
149.7-9	Hand wash Sink		S	22:38
149.7-10	RM 6	21-04-04642	S	22:3
149.7-12	Rm 5		S	22:40
149.7-13	Clinic Bathroom		S	22:4
149.7-14	Clinic	Due Date:	S	22:42
149.7-16	RM 4	06/01/2021	S	22:4
149.7-17	RM 4	(Tuesday)	В	22:4
149.7-19	RM 3	- AE	S	22:4
149.7-20	RM 3		В	22:4
149.7-21	RM 2		S	22:4

Please e-mail lab results to labs@stohlenv.com	lf checked, al	so e-mail results to: <u> </u>	Ehenderson@StohlEnv.com
Sampled By: Paul Nichols	Print Name Stohl	l Env: Paul Nichols	Date: 3/19/2021
Relinquished By: 2. +4-l-Q	Print Name Stohl	I Env: Eric Henderson Jr.	Date: 3/22/2021
Received (Name / Lab):	Date	4.27.21	Time: 11:05 AM
Sample Login (Name / Lab): Tran Bloom	frau Blan Date	: <u>617/21</u>	Time: 916Am
Analysis (Name / Lab):	Oll Date	:_411121	Time: 335pm
QA/QC Review (Name / Lab):	C Date	: _ (11VI	Time: Upm
Archived / Released:QA/QC InterLAI	B Use: Date	MANAGEMENT OF THE PARTY OF THE	Time:



Chain of Custody Document

Submitted to: (Lab Name)

STOHL Job#

EHS

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092

2020L-149.7

	WWW.STOHLENVIRONMENTAL.COM			
Client:	Niagara Falls CSD	Contact: Ea	rl Smeal	
Building:	Maple Ave Elementary School	Location: 95	2 Maple Ave. Niagara Falls, NY	
LEAD			Turnaround	
Water by	SM 19, 21 - 23 3113B (-04, -10)	X	20 Days	

Sample #	Location	Outlet Type	Time
149.7-22	RM 2	В	22:48
149.7-23	RM 1	S	22:49
149.7-24	RM 1	В	22:50
149.7-25	Boys Bathroom Left	S	22:51
149.7-26	Girls Bathroom Left	S	22:52
149.7-27	RM 22	S	22:53
149.7-29	RM 21	S	22:54
149.7-30	Rm 21	В	22:55
149.7-31	RM 20	S	22:56
149.7-32	RM 20	В	22:57
149.7-33	Girls Bathroom Left	S	22:58
149.7-38	Boys Bathroom Left	S	22:59
149.7-39	RM 9	S	23:00
149.7-42	Custodians Office	S	23:01
149.7-44	Kitchen IM	IM	23:02
149.7-45	Kitchen Sprayer	S	23:03
149.7-46	Boys Bathroom Near Cafe Middle	S	23:04
149.7-47	Boys Bathroom Near Cafe Right	S	23:05

Please e-mail lab results to	labs@stohlenv.com		Ehenderson@StohlEnv.com
Sampled By: Paul Nic	chols Print Name	Stohl Env: Paul Nichols	Date: <u>3/19/2021</u>
Relinquished By:	Print Name	Stohl Env: Eric Henderson Jr.	Date: <u>3/22/2021</u>
Received (Name / Lab):	KHARBIONUS	Date: 4.21.21	Time: 11:05 AM
Sample Log in (Name / Lab): Trace & complete Blow	Date: 5/7/21	Time: <u>919 Am</u>
Analysis (Name / Lab):	Sam Oll	Date:	Time: 2 1352
QA/QC Review (Name / La	16): Milled	Date:	Time: Upw
Archived / Released:	QA/QC InterLAB Use:	Date:	Time:

Notes:



Chain of Custody Document

Submitted to: (Lab Name)

3860 California Road, Orchard Park, New York 14127 PHONE (716) 312-0070 FAX (716) 312-8092 WWW.STOHLENVIRONMENTAL.COM

EHS	3
-----	---

STOHL Job#

2020L	-149.	7

\sim	li a	nt	
l d	ш	nt	
•			•

Niagara Falls CSD

Contact: Earl Smeal

Building: Maple Ave Elementary School

Location: 952 Maple Ave. Niagara Falls, NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

Turnaround

20 Days

Sample #	Location			
149.7-48	Rm 6 Bubble			
149.7-49	Rm 5 Bubble			
149.7-50	Admin Room BR			
149.7-51	Boys Locker Room			
149.7-52	Girls Locker Room			
149.7-53	1st Floor Girls BR Near Stairs Middle			
149.7-54	1st Floor Girls BR Near Stairs Right			
149.7-55	1st Floor Boys BR Near Stairs Middle			
149.7-56	1st Floor Boys BR Near Stairs Right			
149.7-57	2nd Floor Girls BR Middle			
149.7-58	2nd Floor Girls BR Right			
149.7-59	2nd Floor Boys BR Middle			

Outlet Type	Time
В	23:06
В	23:07
S	23:08
S	23:09
S	23:10
S	23:11
S	23:12
S	23:13
S	23:14
S	23:15
S	23:16
S	23:17
	<u> </u>

Please e-mail lab results to lab	Ehenderson@StohlEnv.com		
Sampled By: Paul Nichols	Print Name	Stohl Env: Paul Nichols	Date: 3/19/2021
Relinquished By:	Print Name	Stohl Env: Eric Henderson Jr.	Date: 3/22/2021
Received (Name / Lab):	KTHARRIS KILLA	Date 4.27.21	Time: 11:0577m
Sample Login (Name / Lab):	Travibloom fran Blow	Date: 5/7/21	Time: 921Am
Analysis (Name / Lab):	Dany Ocl	Date:	Time: <u>21350m</u>
QA/QC Review (Name / Lab):	Mehlul	Date:	Time:
Archived / Released:	QA/QC InterLAB Use:	_Date:	Time: